

Project Name/Location:

Contract Number: W9127N-05-C-0012

Columbia River Channel Improvement - RM 14+45 to 16+10**Date: 09/29/2005**

<div>Dredging</div> <div><u>Load Number</u></div> <div>919</div> <div><u>Tidal Stage</u></div> <div>Ebb</div> <div><u>Dredge State:</u></div> <div>Overflow through side discharge</div> <div><u>Weather:</u></div> <div>Foggy/Raining</div> <div><u>Wind:</u></div> <div>20-25 kts</div> <div><u>Seas:</u></div> <div>2-3'</div> <div><u>Disposal location</u></div> <div>Columbia River DWS</div>	Sample Point	Depth (ft)	Time	X Coordinate	Y Coordinate	Turbidity (NTU)	DO (Mg/L)
	DR-1	20.2	18:07:21	7363708.66	941529.82	1.0	
	DR-2	22.2	18:08:58	7363363.54	941148.55	12.0	8.5
	DR-2R1	22.6	18:09:01	7363363.54	941148.55	14.4	8.3
	DR-4	20.0	18:11:32	7362697.92	940883.87	20.7	
	DR-4R1	19.7	18:11:37	7362697.92	940883.87	14.9	
	DR-3	20.4	18:14:13	7364051.04	941947.71	11.9	
	DR-3R1	19.8	18:14:18	7364046.83	941947.88	8.4	
Remarks:				Action Taken:			
DR-2 exceeded 10% over background, taken in the plume.				Re-test DR-2R1 was taken.			
DR-4 exceeded 10% over background, taken in the plume.				Re-test DR-4R1 was taken.			
DR-3 exceeded 10% over background, taken out of the plume, on port side.				Re-test DR-3R1 was taken.			
				The dredge moved away from the area while continuing dredging to avoid further increasing the turbidity at the location where the exceedence was measured. The dredge coordinates were marked on the GPS screen to insure no further dredging occurred at the location where the exceedence was measured.			
Sample Point Key	All Tests Conducted With YSI 6600					Turbidity Compliance	DO Compliance
DR-1	Background - 100' Up Current, Within 600-Foot of Channel					OR WA WA	OR, WA Not Required Not Required
DR-2	100' Down Current						
DR-3	300' Radially from point of dredge (Port or Starboard)						
DR-4	900' Down Current from point of dredging						
Rx	Indicates a Re-Test where (x) is the Re-Test number for that particular point						